

10 / 747 953

Cofc#



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Letters Patent of )  
)  
Robert Raymond Arcykiewicz et al )  
)  
Patent No. 6,939,178 B2 )  
)  
Issue Date: September 6, 2005 )  
)  
For: FUEL INJECTOR CONNECTOR )

Atty. Docket: 111418.00410

**Certificate**  
**FEB 13 2006**  
**of Correction**

**REQUEST FOR CERTIFICATE OF CORRECTION**  
**PURSUANT TO 37 C.F.R. §1.322 AND §1.323**


Commissioner for Patents  
Washington, D.C. 20231

Sir:

On behalf of Amphenol Corporation, assignee of the above-identified U.S. patent, a Certificate of Correction for this patent is respectfully requested to correct errors appearing in this patent.

Duplicate copies of form PTO-1050 are attached to affect correction of these errors by Certificate of Correction. A check in the amount of \$100.00 is also attached to cover the fee for the Certificate of Correction.

Prompt issuance of a Certificate of Correction is respectfully requested.

Respectfully submitted,  
  
Charles R. Wolfe, Jr.  
Registration No. 28,680

Customer No. 27557  
BLANK ROME LLP  
Watergate, 600 New Hampshire Ave., N.W.  
Washington, DC 20037  
(202) 772-5800

02/09/2006 JADD01 00000074 6939178  
01 FC:1811 100.00 OP

111418.00410/35711273v.1

**FEB 14 2006**

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO : 6,939,178 <sup>B2</sup>

DATED : September 6, 2005

INVENTOR(S) : Robert Raymond Arcykiewicz et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the face of the patent, under "(56) References Cited, column 2, correct the name of the inventor of U.S. Patent No. 6,328,321 to --Ording et al.--; same line, change the U.S. Cl. from "280/86.754" to --239/585.1; 239/590.3--.

Col. 1, line 32, change "problem" to --problems--;

line 47, change "add" to --and--.

Col. 2, line 23, change "a identification" to --an identification--.

Col. 5, lines 19 and 21, change "male pins" to --male plugs--;

line 30, change "as" best shown" to --as best shown--.

Col. 6, claim 1, line 39, after "assembly" insert a semi-colon --;--.

Col. 8, claim 10, line 5, after "assembly" insert a semi-colon --;--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,939,178

No. of add'l copies @ \$.30 per page

BLANK ROME LLP  
600 NEW HAMPSHIRE AVENUE, N.W.  
WASHINGTON, DC 20037  
TEL (202) 944-3000  
FAX (202) 572-8398

⇒ \_\_\_\_\_

FEB 14 2006

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO : 6,939,178 *B2*

DATED : September 6, 2005

INVENTOR(S) : Robert Raymond Arcykiewicz et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the face of the patent, under "(56) References Cited, column 2, correct the name of the inventor of U.S. Patent No. 6,328,321 to --Ording et al.--; same line, change the U.S. Cl. from "280/86.754" to --239/585.1; 239/590.3--.

Col. 1, line 32, change "problem" to --problems--;

line 47, change "add" to --and--.

Col. 2, line 23, change "a identification" to --an identification--.

Col. 5, lines 19 and 21, change "male pins" to --male plugs--;

line 30, change "as" best shown" to --as best shown--.

Col. 6, claim 1, line 39, after "assembly" insert a semi-colon --;--.

Col. 8, claim 10, line 5, after "assembly" insert a semi-colon --;--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,939,178

No. of add'l copies @ \$.30 per page

BLANK ROME LLP  
600 NEW HAMPSHIRE AVENUE, N.W.  
WASHINGTON, DC 20037  
TEL (202) 944-3000  
FAX (202) 572-8398

⇒ \_\_\_\_\_

FEB 14 2006